

Reading assignment

- Askeland and Phule, The Science and Engineering of Materials, 4th Ed., Ch. 19 and Sec. 6-2.
- Shackelford, Materials Science for Engineers, 6th Ed., Ch. 18.
- Chung, Composite Materials, Ch. 9.







Applications:

Delectrical motors and generators

□transformers,

□to store and retrieve information on magnetic tape or in computers,

Dactuators and sensors,

□to focus electron beams,

Devices: MRIs



A unit of magnetic moment is simply the strength of the magnetic field associated with the electron. This moment, called the Bohr magneton

= $[(q \cdot h)/(4p \cdot m_e)]$ = 9.27 x 10⁻²⁴ A·m²

	financian .		
	and cgs enu (Electromagnetic Units)	ST Units	Conversion
Inductance or magnetic Rue density (18)	Geurs (G)	Tenia for archirr $(W(\partial m^2)$	$1 \ \text{Imm}a = 10^4 \ \text{G}, \ \text{Mbder}^2$
Magnetic flue (a)	Minut (Ma), G-cm ²	Why well descend	1 WD 10 ⁸ G-cm ²
Magnetic potential difference or magnetic electromotive force (G, P)	Gilbert (00)	Aimpiene (A)	$1~A \sim 4\pi + 10^{-1}~\text{Us}$
Magnetic field alrength, magnetizing force (M)	Gersted (Oe), Gilbert (CEO); m	Alter	$1~\mathrm{A}/\mathrm{m}=4\pi \times 10^{-3}~\mathrm{Os}$
Malamet magnetization (M)	emutory ^a	Alte.	1 Am = 10 ⁻² emulan ⁴
Magnetic polarization or etternity of inagnetization Gravity	enut:m ¹	T, Woles ²	$1 \text{ tenso} = (1/4e) = 10^4 \text{ emutors}^2$
Maus) magnetization (e, M)	end	A in ² Ag We mile	1 1 Wo-rivles (1/4e) =- 10 ² error)
Magnets: moment (int)	ans, eggs	A cer ⁸ , Journs 10 per- tenia (DT)	1 #1 - 10 ⁹ etsi
Magnetic dipose moment L()	emu, erg/Q	Wb m	1 Wb-01 = (1,4e) = (0 ²⁰ ems)
Magnetic permeatibility (,a)	Oriensociess	Wolf-m, theny (Hilm)	1 Work m - (1:4e) = 107
Magnetic permeability of tree space (pp)	1 gaves/stroked	$\mu_0 \rightarrow (4\pi) \approx 10^{-3}$ Mins Defined	
Relative permitability (up.)	Not defined	Dumensionista.	terraria casta da taor
Intriume) energy denicity, energy product (W)	etgtau?	York.	$1.3m_{\rm s}\sim 10~{\rm edlym}_{\rm s}$

3d transi	3d transition metals						
Atomic number	Element						
21	Sc						
22	n						
23	v						
24	Cr						
25	Mn						
26	Po						
27	Co						
28	Ni						
29	Cai						

Atomic number	Element	Electronic structure of 3d	Memeat [a_g]
21	S¢		1
22	Tī		2
23	v	+ + +	3
24	Cr	* * * * *	5
25	Mn	+ + + +	5
26	Fø	++ + + +	4
27	Co	4+ + + + +	3
28	Ni	4¥ #¥ #¥ #	2
29	Cu	44 44 Av Av Av	0
		4=0	electronic spin orientation



- □ Cu and Cr have unpaired 4s e -s and their magnetic moments is cancelled by their interactions. Cu has a completely filled 3d shell and thus does not display a net moment.
- □ The e_{s}^{-} in the 3d level of remaining transition elements do not enter the shells in pairs. For Mn, the first five e_{s}^{-} have the same spin.
- □ Only after half of the 3d-level is filled, do pairs with opposing spins form.
- □ Therefore, each atom in a transition metal has a permanent magnetic moment, which is related to the number of unpaired electrons → each atom behaves as a magnetic dipole.

□Recall that each energy state can contain 2 e_{s}^{-} , with opposite spins. If an energy state is full - no net magnetic moment.

- □It may be concluded, that any element with an odd atomic # would have a net magnetic moment. Not true!. ____
- □In most of these elements, the unpaired eis a valence e-, and due to their frequent interactions the magnetic moments, on average, cancel each other and no net magnetic moment is associated with the material.

- □ The response of the atom to an applied magnetic field depends on how magnetic dipoles represented by each atom react to the field.
- Most of the transition elements react in such a way that the sum of the individual atoms' magnetic moments is zero.
- Nickel, iron, and cobalt undergo an exchange interaction, whereby the orientation of the dipole in one atom influences the surrounding atoms to have the same dipole orientation, producing a desirable amplification of the effect of the magnetic field.



- Ferromagnetism Alignment of the magnetic moments of atoms in the same direction so that a net magnetization remains after the magnetic field is removed.
- Ferrimagnetism Magnetic behavior obtained when ions in a material have their magnetic moments aligned in an antiparallel arrangement such that the moments do not completely cancel out and a net magnetization remains.
- Most widely used magnetic materials are based on ferromagnetic metals and alloys such as Fe, Ni, and Co or ferrimagnetic ceramics (ferrites & garnets).
- Magnetic behavior is determined primarily by the electronic structure of a material, which provides magnetic dipoles.
- □ Interactions between these dipoles determine the type of magnetic behavior that is observed.
- Magnetic behavior can be modified by composition, microstructure, and processing of these basic materials.

Diamagnetism - The effect caused by the magnetic moment due to the orbiting electrons, which produces a slight opposition to the imposed magnetic field.







- permanent magnetic dipoles are oriented by an interaction between the magnetic material and a magnetic field, H.
- Magnetization enhances the influence of the magnetic field; allows larger magnetic energies to be stored.
- □ This energy can be stored permanently or temporarily and can be used to do work.
- Each electron in an atom has two magnetic moments (spin and orbital contributions).





□When a magnetic field is applied in a vacuum, lines of magnetic flux are induced. The number of lines of flux, called the flux density, or inductance B, where B = m.H.

magnetic permeability-----

□When we place a material within the magnetic field (H), B is determined by how the induced and permanent magnetic dipoles interact with H. The inductance is now: $B = \mathbf{m} \cdot \mathbf{H}$

Permeability of material in the field

□ If the magnetic moments reinforce the applied field, then **m**>**m**, a greater # of lines of flux are created, and H is magnified.

□ If the magnetic moments oppose the field, then

m< m..

□ The influence of the magnetic material can be described by the relative permeability **m**

 $\mathbf{m} = (\mathbf{m} \mathbf{m})$. A large \mathbf{m} means that the material amplifies the effect of the magnetic field.

The magnetization M represents the increase in the inductance due to the core material:

 $= 10^4$ gauss

□For important magnetic materials, the term mM >> mH, thus:

B@m, M

□Inductance, B, or magnetization, M, are sometimes used interchangeably, though they are not the same.

 \Box High B or M is achieved by selecting materials with high \mathbf{m}

 $= 10^4$ gauss









Paramagnetism

- \Box occurs in materials with unpaired e⁻_s.
- □ a net magnetic moment due to e spin is associated with each atom.
- □ when H field is applied the dipoles line up with the field, causing a positive magnetization.
- because the dipoles do not interact, extremely large magnetic fields are required to align all of the dipoles.
- □ the effect is lost as soon as the magnetic field is removed.
- □ it is found in AI, Ti, and Cu alloys.

□ m = 1.0 - 1.01



Ferromagnetism

- □ Coupling interactions develop ⇒ alignment of net spin magnetic moments of adjacent atoms, even when no external field acting.
 □ large magnetizations
- are obtained even for small magnetic fields. m = very high, 10⁶



Antiferromagnetism:

- □It occurs in materials such as Mn, Cr, MnO, and NiO.
- The magnetic moments produced in neighboring dipoles line up in opposition to one another in the H. Zero magnetization!!

Antiferromagnetism - Arrangement of magnetic moments such that the magnetic moments of atoms or ions cancel out causing zero net magnetization.





MnO crystal structure: alternating layers of (111) type planes of O and Mn ions. The magnetic moments of the Mn ions in every other (111) plane are oppositely aligned.

Ferrimagnetism

- □ It occurs in ceramic materials.
- Different ions have different magnetic moments.
- Dipoles of ion A line up with H, while dipoles of ion B oppose H.
- □ Since the strengths of the dipoles are different, there is a net magnetization.
- Ceramic ferrites have this behavior

Fe₃O₄ (magnetite)

For every four O²⁻ ions, there must be one Fe²⁺ ion and two Fe³⁺ ions in order to have electrical neutrality









lon positions in a subcell

- O²⁻ ions occupy the corners and face centers.
- Fe²⁺ ions occupy ¹/₄ of the octahedral interstitital sties (formed by the anion structure)
- Fe³⁺ ions occupy ¹/₄ of the octahedral interstitial sites and 1/8 of the tetrahedral interstitial sites.







 $= 1 + 12(\frac{1}{4}) = 4$

Body-	Edge-centered sites;
centered	12 edges, each
site	shared by 4 cubes.











No. of ions per subcell

- Fe²⁺ ions: 4 octahedral interstitial sites per subcell times ¹/₄ = 1
- Fe³⁺ ions: 4 octahedral interstitial sites per subcell times ¹/₄ + 8 tetrahedral interstitial sites per subcell times 1/8 = 2

Magnetic alignment of ions

- O²⁻ ions have zero magnetic moment.
- The ions in the octahedral interstitial sites and those in the tetrahedral interstitial sites are opposing alignment.



Magnetic moment of the ions

- Fe²⁺ ion (3d⁶) 4 Bohr magnetons
- Fe³⁺ ion (3d⁵) 5 Bohr magnetons

Magnetic moment per cell

- Octahedral Fe²⁺ (1 per subcell) (spin up): +4 Bohr magnetons
- Octahedral Fe³⁺ (1 per subcell) (spin up): +5 Bohr magnetons
- Tetrahedral Fe ³⁺ (1 per subcell) (spin down):
 -5 Bohr magnetons
- Total per subcell = +4+5-5
 - = +4 Bohr magnetons
- Total per true unit cell = +4 X 8 = +32 Bohr magnetons.

Saturation magetization

Magnetic moment per unit cell, divided by volume of unit cell

= 32 (9.27 X 10^{-24} A.m²)/(8.37 X 10^{-10} m)³ = 5 X 10^{5} A.m⁻¹

NiFe₂O₄ (nickel ferrite)

- Ni²⁺ instead of Fe²⁺
- Magnetic moment for a Ni²⁺ ion = 2 Bohr magneton
- Magnetic moment per true unit cell = +16 Bohr magnetons

Magnetic moments for ions in the spinel structure					
lon	Bohr Magnetons				
Fe ³⁺	5				
Mn ²⁺	5				
Fe ²⁺	4				
Co ²⁺	3				
Ni ²⁺	2				
Cu ²⁺	1				
Zn ²⁺	0				

The high electrical resistivity of these ceramic compounds helps minimize eddy currents and allows the materials to operate at high frequencies.



(a) A qualitative sketch of magnetic domains in a polycrystalline material. The dashed lines show demarcation between different magnetic domains; the dark curves show the grain boundaries.

Domain structure

- Ferromagnetic materials have a powerful influence on magnetization because of the positive interaction between the dipoles of neighboring atoms.
- A substructure composed of magnetic domains is produced within the grain structure of a ferromagnetic material, even in the absence of an external field.
- Domains are regions in the material in which all of the dipoles are aligned.
- In a material that has never been exposed to a magnetic field, the individual domains have a random orientation.



(b) The magnetic moments in adjoining atoms change direction continuously across the boundary between domains.

- The net magnetization in the material as a whole is zero.
- Boundaries, called Bloch walls separate the individual domains.
- The Bloch walls are narrow zones in which the direction of the magnetic moment gradually and continuously changes from that of one domain to that of the next.
- The domains are typically very small, about 0.005 cm or less.
- The Bloch walls are about 100 nm thick.

- When a H is imposed on the material, domains that are nearly lined up with the field grow at the expense of unaligned domains.
- □For the domains to grow, the Bloch walls must move; H provides the force required for this movement.
- □Initially the domains grow with difficulty, and relatively large increases in the field are required to produce even a little magnetization.









When a magnetic field is first applied to a magnetic material, magnetization initially increases slowly, then more rapidly as the domains begin to grow. Later, magnetization slows, as domains must eventually rotate to reach saturation. Notice the permeability values depend upon the magnitude of H.









(a) The ferromagnetic hysteresis M-H loop showing the effect of the magnetic field on inductance or magnetization. The dipole alignment leads to saturation magnetization (point 3), a remanance (point 4), and a coercive field (point 5).

(b) The corresponding B-H loop. Notice the end of the B-H loop, the B value does not saturate since $B = \mu_0 H + \mu_0 M$.

Effect of removing the magnetic field

□Because of the resistance by the domain walls, domains do not regrow into random orientations.

Many domains remain oriented near the direction of the original field.

Residual magnetization, remanence,(B,) is present in the material.



By alternating the applied field a hysteresis loop results.





Soft magnetic materials

- used to enhance the magnetic flux density (B) produced when an electric current is passed through the material. Applications include cores for electromagnets, electric motors, transformers, generators, and other electrical equipment.

Magnetic materials for electrical applications

Electrical magnetic materials are called *soft magnets*.
 Characteristics:

- 1. High saturation magnetization \rightarrow allows a material to do work.
- 2. High permeability > saturation magnetization reached @ small H_{applied}
- 3. Small coercive field. $\textbf{ \rightarrow }$ domains can reoriented with small $\textbf{H}_{\text{applied}}$
- 4. Small remanence → desired, so that no magnetization remains when H_{applied} is removed.
- 5. Small hysteresis loop → minimizes energy losses.
- 6. Rapid response to high-frequency magnetic fields.
- 7. High electrical resistivity.

Magnetic materials for electrical applications

- □ If frequency of *H*_{applied} is too high that domains do not realign in each cycle → device may heat due to dipole friction.
- Higher frequencies produce more heating!!
 material cycles through the hysteresis loop more often.
 - → energy is lost during each cycle.
- Energy can also be lost by heating if eddy currents are produced.
- □ During operation, electrical currents can be induced into the magnetic material → these currents produce power losses and Joule heating (^βR).

Magnetic materials for electrical applications

- If the electrical resistivity is high, eddy current losses can be held to a minimum.
- Soft magnets produced from ceramic materials have a high resistivity and therefore are less likely to heat than metallic magnets.

		Perme	billy (a,)	Course of the				
Name	Composition	Initial	Maximum	(H _c) (A - m ⁻¹)	(8.) (7)	(7)	(eΩ-m)	
ingst Iron	99.8% Fe	150	5000	80	0.77	2.54	0.20	
Low-carbon steel	199.5% Fe	200	4000	100		2.14	1.12	
Silicon iron, unoriented	Fe-3% Si	220	8000	-60		201	0.47	
Silicon iron, ghuin-oriented	7e-3%.5i	1400	50.000	3	1.20	2.01	0.50	
#750 alkay	Fe-40% N	11,000	80.000	2		1.55	0.48	
4-79 permatos	Fe-4% Mo-79% Ni	40.000	200.000	1		0.80	0.58	
Superaday	Fe-5% Mis-80% N	80.000	450.000	0.4		0.78	0.65	
2V-Permendul	762% Y-99% OF	800	450,000	0.4		0.28	0.65	
Supermenduz	76-25 V-495 Ci		100.000	16	2.00	2.30	0.40	
Metglan [#] 26500C	PhullensSturfe		300.000	- 3	2.46	1.61	1.35	
Wegen® 26505-2	BengButhe		600.000	2	1.35	1.56	1.32	
Mr.Zr. Feetle	H6C2 ⁿ	10,000		.7	0.09	0.40	1.5×10^{9}	
Mo2n Femile	HEL*	18.000		2	0.12	0.44	5×104	
Ni2n Femile	#15 ^m	290		80	0.25	0.33	2×10^{10}	
*Alled Corporators 1 *10K Rente code Gource: Adapted fo G.Y. Only et al. 11 K	raturark en Magnetic Malerials Discr. M. Flemings, an	Ar Oursin I.S. Mahaja	c Hair Cro r IDAL Dry	utt, Magretic Musi cigoda il Athançe	universiti, Magner d Materialis, Voc. J	tottutue 1. 2094, J	Materials," fa 1424, Tatale	

Hard magnetic materials -

used to make strong permanent magnets

Strong permanent magnets, often called hard magnets.

□Requirements:

- 1. High remanence (stable domains).
- 2. High permeability.
- 3. High coercive field.
- 4. Large hysteresis loop.
- 5. High power (or BH product).

Hard magnet -

Ferromagnetic or ferrimagnetic material that has a coercivity > $10^4 \text{ A} \cdot \text{m}^{-1}$.

2.5 Saturation magnetization µ₀M(T) Cofe Fo, FoSi C-4 Fern BanS Pe RCO Soft ferri 010-1 100 101 102 103 104 105 106 Coercivity, HcJ (A m-1) Soft -Semihard + Hard (b)

Material	Common Name	μ ₀ Μ ₇ (T)	μ _ο Η _ε (T)	(BH) _{max} (kJ - m ⁻³)	T _c (°C
Fe-Co	Co-steel	1.07	0.02	6	887
Fe-Co-Al-Ni	Alnico-5	1.05	0.06	44	880
BaFe ₁₂ O ₁₉	Ferrite	0.42	0.31	34	469
SmCo ₅	Sm-Co	0.87	0.80	144	723
Nd ₂ Fe ₃₄ B	Nd-Fe-B	1.23	1.21	290-445	312

The behavior of a material in a magnetic field is related to the size and shape of hysteresis loop.

Magnetic materials for permanent magnets

Strong permanent magnets, often called hard magnets.

Requirements:

- 1. High remanence (stable domains).
- 2. High permeability.
- 3. High coercive field.
- 4. Large hysteresis loop.
- 5. High power (or BH product).







Power - The strength of a permanent magnet as expressed by the maximum product of the inductance and magnetic field, i.e., the BH product.

BH product is related to the power, or energy, required to demagnetize the permanent magnet.

- □The power of the magnet is related to the size of the hysteresis loop, or the maximum product of B and H.
- □The area of the largest rectangle that can be drawn in the second or fourth quadrants of the B-H curve is related to the energy required to demagnetize the magnet.
- □For the product to be large, both the remanence and the coercive field should be large.



The Curie temperature

- □In ferromagnetic materials as T s, the mobility of the domains - s, making it easier to become aligned, but this also prevents them to remain aligned when the field is removed.
- \Box saturation magnetization, remanence, and the coercive field are all ⁻ed at T_{high}.
- □If $T > T_{curie} \rightarrow$ ferromagnetic behavior changes to paramagnetic behavior

Curie temperature (T_c)

The temperature above which a ferromagnetic or ferrimagnetic material becomes paramagnetic.





TABLE 19-3 ■ Curie temperatures for selected materials						
Material	Curie Temperature (°C)					
Gadolinium	16					
Nd ₂ Fe ₁₂ B	312					
Nickel	358					
BaO · 6Fe ₂ O ₃	469					
Co ₅ Sm	747					
Iron	771					
Alnico 1	780					
Cunico	855					
Alnico 5	900					
Cobalt	1117					



Magnetic materials for computer memories

Dused to store bits of information in computers.

- Memory is stored by magnetizing the material in a certain direction.
- Materials with a square hysteresis loop, a low remanence, a low saturation magnetization, and a low coercive field are preferable.
- Ferrites containing Mn, Mg, or Co may satisfy these requirements.
- The square loop assures that a bit of information placed in the material by a field remains stored.



Information can be stored or retrieved from a magnetic disk by use of an electromagnetic head. A current in the head magnetizes domains in the disk during storage; the domains in the disk induce a current in the head during retrieval.



- Information can be stored or retrieved from a magnetic disk by use of an electromagnetic head.
- A current in the head magnetizes domains in the disk during storage.
- The domains in the disk induce a current in the head during retrieval.

Data storage applications

- Memory
- Stripe on credit cards
- Audio-cassettes

	Paticle		Magnetia	ration $(B_{\rm f})$	Coercivi	ty (He)	Surface Area m²/g	Carie temp. (T _p) *C
	/fl	Ratio	Wb/m²	enuicc	k4/m	De		
-FeyDy	0.20	51	0.44	350	22-34	420	15-30	600
Co-7-FegOa	0.20	61	0.48	380	30-75	940	20-35	700
002	0.20	10-1	0.50	400	30-75	950	18-55	125
Fé	0.15	10:1	1.40*	1100 ^a	56-176	2200	20-60	770
Barium Femile	0.05	0.02 pm thick	0.40	320	56-240	3000	20-25	350

Magnetocrystalline anisotropy - In single crystals, the coercivity depends upon crystallographic direction creating easy and hard axes of magnetization.



The initial magnetization curve for iron is highly anisotropic; magnetization is easiest when the <100> directions are aligned with the field and hardest along [111].







Magnetostriction

- Strain due to change in magnetic state (by changing the magnetic field or the temperature)
- Due to interaction of the magnetic field with the electron orbit
- Examples of magnetostrictive materials: iron nickel, Fe₃O₄, TbFe₂, DyFe₂, SmFe₂.
- Useful for actuation





-																	
IA																	0
1																	2
H	TT A											III A	TV/ A	X/ A	VT A	AUT A	He
1.008	ПA	,										mA	IVA	VA	VIA	VIIA	4.003
3	4											5	6	7	8	9	10
Li	Be											B	C	N	0	F	Ne
0.941	9.012											10.81	12.01	14.01	16.00	19.00	20.18
11 No	12 Ma							VIII				15	14 s:	15 15	16		18
22.99	24 31	III B	IV B	VB	VI B	VII B				I B	II B	26.98	28.09	30.97	32.06	35.45	39.95
19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36
K	Ca	Sc	Ti	v	Cr	Mn	Fe	Co	Ni	Cu	Zn	Ga	Ge	As	Se	Br	Kr
39.10	40.08	44.96	47.90	50.94	52.00	54.94	55.85	58.93	58.71	63.55	65.38	69.72	72.59	74.92	78.96	79.90	83.80
37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54
Rb	Sr	Y	Zr	Nb	Mo	Tc	Ru	Rh	Pd	Ag	Cd	In	Sn	Sb	Te	I	Xe
85.47	87.62	88.91	91.22	92.91	95.94	98.91	101.07	102.91	106.4	107.87	112.4	114.82	118.69	121.75	127.60	126.90	131.30
55	56	57	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86
Cs	Ba	La	Hf	Ta	W	Re	Os	Ir	Pt	Au	Hg	11	РЬ	Bi	Po	At	Rn
152.91	157.33	138.91	1/8.49	180.95	183.85	186.2	190.2	192.22	195.09	196.97	200.59	204.57	207.2	208.98	(210)	(210)	(222)
8/ En	88	89	104	105	100												
(223)	226.03	(227)	(261)	(262)	(266)												
(445)	220.00	(221)	(201)	(202)	(200)												
		58	59	60	61	62	63	64	65	66	67	68	69	70	71		
		140.12	Pr 140.01	Nd 144.24	Pm (145)	5m 150.4	EU 151.06	157.25	158.02	162 50	H0	Er 167.26	168.02	172.04	174.07		
		140.12	01	02	(143)	0.4	05	137.23	136.95	102.50	00	107.20	108.95	102	1/4.97		
		- 50 Th	Pa	92	Nn	94 Pu	30 Am	0 0 0	Bk	98 Cf	- 59 Fs	Fm	Md	102 No	105 I.w		
		232.04	231.04	238.03	237.05	(244)	(243)	(247)	(247)	(251)	(254)	(257)	(258)	(259)	(260)		





















 Stress cycle
 Comments

 On
 Off

 Specimen is loaded to a given stress and subsequently unloaded

 Time
 Viscoelastic: some instantaneous elastic strain followed by elastic strain which increases with time under stress and recovers slowly; some viscous (plastic) flow may also occur

 Time
 Image: stress and subsequently unloaded

Viscoelastic material

- A material in which the total strain developed has elastic and viscous components.
- Part of the total strain recovers similar to elastic strain.
- Some part of the total strain recovers over a period of time.
- Examples: polymer melts.

Viscosity

- Measure of resistance to flow
- Defined as the ratio of shear stress to shear strain rate
- Unit: Poise or Pa.s
- 1 Pa.s = 10 P = 1000 cP













Table 1. Typical properties of MR and ER fluids								
	MR fluids	ER fluids						
Maximum yield stress	50-100 kPa	2-5 kPa						
Plastic viscosity	0.2-1.0 Pa.s	0.2-1.0 Pa.s						
Maximum field	~ 250 kA/m	~4 kV/mm						
Response time	ms	ms						
Density	3-4 g/cm ³	1-2 g/cm ³						
Operable temperature	-50 to 150°C	+10 to 90°C						
range								
Power supply	2-25 V	2000-5000 V						
	1-2 A	1-10 mA						
	(2-50 W)	(2-50 W)						
Stability	Not affected by	Cannot tolerate						
	most impurities	impurities						